# DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt Governor Kathleen Clarke Executive Director

Lowell P. Braxton Division Director 801-538-7223 (TDD)

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax)

# INSPECTION REPORT

Partial	XXX	Complete _	Explo	ration	
Inspection Dat		002 / Time: 8:			M
1		ate of Last Inst			

Mine Name: Des Bee I	Dove Mine	County: Emery	Permit Number: <u>C/015/017</u>
Permittee and/or Opera	tor's Name: PacifiCon	rp	
Business Address:	P.O. Box 310, Huntin	igton, Utah 84528	
Company Official(s): _	Dennis Oakley		
State Official(s):	Jim Smith	Federal Official(s):	
Weather Conditions:	Cold, sunny, clear, 1	ight breeze	
Type of Mining Activity	y: Underground XXX	_SurfacePrep Pla	antOther
Existing Acreage: Pern	nitted 2760 Disturb	ed_24 Regraded _	Seeded
Status: Active XXX		_	

# REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE				
2.	SIGNS AND MARKERS	[X]		[X]	
3.	TOPSOIL	[X]			$\Box$
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS		$\Box$		
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[X]	$\Box$	[X]	
c.	OTHER SEDIMENT CONTROL MEASURES		$\Box$		
d.	WATER MONITORING	$\Box$	$\Box$		
e.	EFFLUENT LIMITATIONS			$\Box$	
5.	EXPLOSIVES	$\Box$	$\Box$		
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	$\Box$	$\Box$		
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[X]	$\Box$	[X]	
8.	NONCOAL WASTE	[X]	$\Box$	[X]	
9.	PROTECTION OF FISH, WILDLIFF, AND RELATED				
,	ENVIRONMENTAL ISSUES		$\Box$		$\Box$
10.	SLIDES AND OTHER DAMAGE	$\Box$	$\Box$		
11.	CONTEMPORANEOUS RECLAMATION	$\Box$			
12.	BACKFILLING AND GRADING	[ <u>X]</u> [_]			
13.	REVEGETATION		$\Box$	$\Box$	
14.	SUBSIDENCE CONTROL		$\Box$		
15.	CESSATION OF OPERATIONS		$\Box$	$\Box$	
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING		$\Box$		
b.	DRAINAGE CONTROLS		$\Box$	$\Box$	
17.	OTHER TRANSPORTATION FACILITIES	$\Box$	$\Box$	$\Box$	
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	$\Box$	$\Box$	$\Box$	
19.	AVS CHECK (4th Quarter- April, May, June)	$\Box$		$\Box$	$\Box$
20.	AIR QUALITY PERMIT	$\Box$	$\Box$		$\Box$
21.	BONDING & INSURANCE	[]		$\Box$	$\Box$

# INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: C/015/017	DATE OF INSPECTION: 02/26/2002
--------------------------	--------------------------------

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

Photographs can be found at:

ftp://dogm.nr.state.ut.us/PUB/MINES/Coal/C015/017/Images/02262002

# 2. SIGNS AND MARKERS

The sign at the mine entry has been vandalized by shooters, but except for the telephone numbers of the Salt Lake and Huntington offices, the necessary information is legible. Dennis Oakley said he would restore the telephone numbers, that afternoon if possible. The operator is disinclined to make a new sign because that may simply invite another episode of vandalization.

### 4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The sedimentation pond has been decanted and has minimal water in it. The pond still needs to be cleaned of sediment, but the operator is waiting to see if reclamation can be done instead, thereby avoiding an additional, unnecessary expense.

### 7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

Coal mine waste has been placed on the bath-house pad and compacted as part of reclamation.

### 8. NONCOAL WASTE

Steel and old tires have been removed from the coal mine waste compacted on the bathhouse pad and generally from anywhere earthwork is done on this site (photo # P0003385 and P0003386). This waste will be disposed of off-site at a landfill. A concrete structure at the Deseret pad has been removed since the last inspection (photo # P0003381), and removal of the concrete supports for a section of an old tram is planned for the immediate future. Concrete will be buried on-site during reclamation.

### 12. BACKFILLING AND GRADING

Coal mine waste has been placed on the bath-house pad and compacted as part of reclamation.

Inspector's Signature:

ames D. Smith #

Date: February 27, 2002

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM

Chuck Semborski, PacifiCorp

Price Field office

O:\015017.DBD\Compliance\2002\p\_0226.doc